



- | | | | |
|--|--|--|--------------------------------|
| | Asbestos air sampling location | | Building demolished |
| | Asbestos, TSP/metals sampling and ambient dust monitoring location | | Decontamination in progress |
| | Debris remains, awaiting disposal | | Demolition in progress |
| | Awaiting asbestos abatement | | Former site railroad (removed) |
| | | | Site boundary |

Basemap source: Esri



EAGLE ZINC OPERABLE UNIT 1
MONTGOMERY COUNTY, HILLSBORO, ILLINOIS

DEMOLITION PROGRESS TRACKING
FEBRUARY 2, 2015

EPA REGION 5 RAC 2 | REVISION 0 | FEBRUARY 2015

